

SCHOOL BUS AND WHEELCHAIR SECUREMENT DEVICE DECAL

The inspection decal is placed on the lower left front corner of the windshield. The decal is punched in the month the bus was inspected and expires 12 months from the month and year it was placed on the windshield.

JAN **MINNESOTA** **JUL**
FEB **STATE PATROL** **AUG**
MAR **COMMERCIAL** **SEP**
VEHICLE INSPECTION
PROGRAM

- This vehicle is in compliance with 49CFR 396.17 Appendix "G" Periodic Annual Inspection
- School Bus Inspection Pursuant to 169.451
- Wheel Chair Securement Devices Pursuant to 299a.11

INSPECTED IN MONTH SPECIFIED
APR **2016** **OCT**
MAY **NOV**
JUN **DEC**

VIN# _____
Serial No. **SAMPLE**

DO NOT DUPLICATE UNDER PENALTY OF LAW

EXAMPLE:



OUTSIDE VIEW



INSIDE VIEW

INTERIM STICKER

The interim sticker is issued to school bus dealers for placement on new school buses into Minnesota.

The dealer must certify to the State of Minnesota by means of a pre-registration certificate, completed before plates are issued, that the bus meets Minnesota Minimum School Bus Standards.

The sticker is valid until the next annual inspection by the State for the owner of the bus. The issue date on the back or inside of the sticker should never be more than 13 months old.



OUTSIDE VIEW



INSIDE VIEW

TEMPORARY DECAL

The temporary sticker is placed on the windshield by an inspector when a bus fails to pass the inspection but is not rejected. The sticker is valid for 14 days. If the State fails to re-inspect the bus within 14 days, the owner or his designee may certify repairs have been made by signing a copy of the School Bus Inspection Deficiency Report (PS 18073) and placing it in the first aid kit.



REJECTION DECAL (Out of service)

The rejection or out-of-service decal, is placed on the windshield in the vicinity of the annual inspection decal. This indicates the bus failed the inspection and cannot be operated until repaired.

The bus may be operated after repair is certified by the owner or his designee by signing the copy of the School Bus Inspection Deficiency Report (PS 18073) and carrying that report in the first aid kit.

The sticker shall be removed only upon authorization from a CVI II or trooper who has determined that the defects that caused the rejection have been corrected.